# Instructions

Assembly Installation Operation

4/2009

### Wellspring ® Litter Surface Mounting Instructions

#### Hardware included for surfacing mounting:

- (4) Stainless Surface Mount Tabs
- (4) #12 Stainless Flat Head Screws


#### Tools required for attaching surface mount tabs:


#2 Phillips Screwdriver

Hand drill with a 11/64 (4.5mm) diameter drill bit

Each surface mount litter is shipped with four mounting brackets and screws to attach them to the litter legs. Each bracket has a 3/8" (9.5 mm) diameter hole for a 5/16 (8.0) diameter anchor.

- 1. Locate the hardware bag shipped with each bench.
- 2. Carefully place litter upside down on a smooth non-abrasive surface, remove the nylon glides from the bottom of the 4 litter legs.
- 3. Using the glide nail hole as a guide, drill an 11/64" (4.5 mm) diameter pilot hole for the flat head screws 1" (25 mm) deep in each leg.
- 4. Attach brackets facing inward with screws.





# Instructions

Assembly Installation Operation

Recommended procedure for surface mounting:

### WARNING! TO AVOID INJURY TO PERSONS HANDLING LITTERS, USE TWO PERSONS TO TEAM LIFT AND CARRY.

Although the anchoring procedure and hardware are the responsibility of the installer, we suggest the following:

- 1. Select corrosion resistant anchors appropriate for the surface. Your hardware store or builders supply may be able to recommend the proper hardware, tools, and safety equipment.
- 2. Place the litter in the desired position.
- 3. Mark the hole locations for anchors.
- 4. Move the litter to allow access for drilling holes.

Install the anchors and litter according to the anchor manufacturer's instructions.